



DESCRIPTION

The Otam 58 Millennium HT is an unmistakable expression of Italian performance and style, combining aggressive lines with exceptional seakeeping and luxurious comfort. Presented with a striking dark grey hull and elegant white deck, this 2011 example has benefited from an extensive refit program carried out by OTAM Shipyard in Genoa, together with continuous upgrades and meticulous maintenance.

Powered by twin Caterpillar engines coupled to Arneson surface drives, both professionally maintained by authorized service centers, she delivers the exhilarating performance for which the Otam brand is renowned. Major works have included extensive mechanical servicing, electrical system upgrades, new batteries, air-conditioning enhancements, generator replacement, and numerous cosmetic improvements throughout the yacht.

Her layout accommodates four guests in two ensuite cabins, featuring a spacious owner's cabin with double berth forward and a comfortable twin guest cabin. Separate crew quarters with private facilities are located forward.

On deck, generous sunbathing areas, a beautifully appointed cockpit with wet bar, upgraded entertainment systems, and numerous comfort features create the ideal setting for entertaining or extended cruising. Comprehensively upgraded and maintained to a high standard, this Otam 58 Millennium HT represents a rare opportunity to acquire one of the most iconic high-performance yachts ever built, where exhilarating performance meets timeless Italian craftsmanship.

Marco Fiorani

+33 6 40 62 37 95 - marco@ideayachting.com

MONACO

SPECIFICATIONS

Builder	Otam
Model	MILLENNIUM 58 HT
Registration Year	2011
Length	16.75 m
Length over all	18.70 m
Beam	4.68 m
Draft	1.30 m
Displacement	32,000 Kg
Engine	2 x 1,730 Hp Caterpillar C23, 1260 hrs
Generator	Kohler (1 x 17.5 Kw), - hrs
Max Speed RPM	52 kn
Cruise Speed RPM	45 kn
Fuel tank capacity Material	3,500 l
Water tank capacity Material	730 l
People transportable	16
Cabins	2
Baths	2
Crew Quarters	1 Cabin ensuite
Visible	Campania, Italy
Price	1,150,000.00 €
Vat	VAT Paid

ACCESSORIES

Navigation equipment

Autopilot Geonav
Compass
Display

GPS Raymarine
Radar
VHF Radio Raymarine

Staging and technical

Batteries
2 Battery charger
Bow Thruster
cockpit table Electric folding with stools
Compressor Air System

Directional Spotlight
Hard top
Platform
swimming ladder
Teak Cockpit

Domestic Facilities onboard

2 Air Conditioning + Tropical in Cockpit
30.000BTU

2 Inverter Victron Energy 24V 1600VA
Warm Water System

Entertainment

Satellite TV antenna
Speakers

TV

Kitchen and appliances

Ceramic hot plate
Freezer
ICE Maker

Refrigerator
Washer dryer Miele WTI370
Winecooler Frigit

Upholstery

Cockpit Cover
Cockpit Cushions
Cushions

Instrument Cover
Seat Cover
Sunshade

FURTHER INFORMATION

Raymarine chain counter
FLIR thermal night vision camera
Cockpit TV with SKY satellite decoder
Master and Guest cabin TVs with SKY satellite decoders
Engine trolling valves
Dual freshwater pressure pumps
Dual air-conditioning circulation pumps
Fusion premium audio system
Seawater intake system
Frequency converter
Voltage transformer
Shore power connection
Cockpit wet bar unit

FURTHER INFORMATION

WORKS 2023

Engine Room:

Removal and reinstallation of main propulsion engines (MEs)

Major overhaul of the main engines, including:

- Replacement of aftercooler cores
- Replacement of primary shaft oil seals
- Complete turbocharger overhaul
- Replacement of turbo compensator bellows
- Overhaul of injection pumps and injectors
- Overhaul of Alfa Laval fuel heat exchanger
- Overhaul of gearbox oil heat exchanger
- Overhaul of freshwater heat exchangers
- Cylinder liner borescope inspection
- Overhaul of freshwater pumps
- Replacement of oil sump gaskets

Installation of trolling valves

Engine and gearbox oil analysis

Routine maintenance (oil, filters, belts)

Repainting of engines

Overhaul of Vulkan cardan shafts by the manufacturer

Overhaul of Arneson surface drives

Replacement of 9.5 kW generator with a new 17.5 kW generator

Replacement of engine room air intake fans (2 + 2 units)

Replacement of air extraction fans

Replacement of Bersey exhaust silencers

Installation of perforated diffusers on stern exhaust outlets

Replacement and upgrade of the generator and chiller cooling circuit

Complete replacement of sound insulation throughout the engine room

Propeller modification by River Walk Marine for improved performance

New electronic control board for the BCS hydraulic control unit

Overhaul of the Opacmare gangway hydraulic power pack

Rebuild of the gangway rotation motor

Installation of rotation speed control valves for the gangway

Air Conditioning System:

Installation of new air-conditioning chiller and associated pumps

Installation of a new seawater intake, pump, and filter for cockpit air conditioning

Electrical System

Replacement of bow thruster batteries

Replacement of generator battery

Relocation of generator and bow thruster batteries to midship, including new cabling

Relocation of generator and bow thruster battery switches beneath the generator for improved accessibility

Installation of a frequency converter and voltage transformer

Replacement and consolidation of the 220V electrical line from shore power connection to

FURTHER INFORMATION

the main switchboard (from two 16 mm² cables to one 35 mm² cable), including new relays

Interior & General Improvements

Modification and refinishing of sole boards

Complete repainting of the engine room

Replacement of lighting throughout the vessel.

Deck Works:

Replacement of incandescent navigation lights with new Lopolight LED navigation lights

Installation of FLIR thermal night vision camera

New mast installed

Replacement of Harken hard-top blocks and complete hard-top overhaul

Re-chroming of aft mooring capstans

Replacement of anchor windlass motor and gearbox

Replacement of upholstery for helm seats, sofas, aft sunpad, and headliner panels

Replacement of cockpit and aft sunpad protective covers

Construction of a new cockpit wet bar unit

Installation of three cockpit air-conditioning units (total capacity: 30,000 BTU)

Installation of a new Fusion/LJ audio system with six loudspeakers and two subwoofers, integrated with the interior audio system

Overhaul of side handrail mountings

Installation of stainless-steel protection plates on the main mooring cleats

Replacement of lighting in the forepeak locker

Repainting of the forepeak locker and chain locker

Replacement of the galvanized anchor with a new stainless-steel anchor

Replacement of fender covers

Interior works:

Installation of five new air-conditioning units (total capacity: 50,000 BTU), including modifications to cabinetry for their accommodation

Installation of a new water distribution line and manifold from the chiller system

Modification of air-conditioning supply and return air vents

Installation of a new 220V refrigerator in the dinette

Installation of a new ice maker in the dinette

Installation of a new Fusion/Bose audio system with six pairs of satellite speakers and two subwoofers

Replacement of mattresses in the starboard guest cabin and owner's cabin

Replacement of LED courtesy/step lights

Replacement of Vimar switch plates and light point covers

Replacement, where necessary, of hinges and push-pull latches on doors and drawers

Cleaning of bilges and inspection of valves, tightening of hose clamps on hose connections, and tightening of manhole cover fastenings

Additional Upgrades & Improvements

Custom perforated sunshade screens for the hard top

Custom perforated cockpit enclosure sunshades

FURTHER INFORMATION

New carpeting installed throughout guest cabins and companionway, matching the original style and colour scheme

New electric toilets and bidet shower systems installed in the Master Cabin and Port Guest Cabin

Interior wood flooring professionally restored, including treatment of darkened areas and local refinishing of affected planks

New engine room air compressor with quick-connect fitting installed aft

New Miele washer-dryer installed, including system modifications and mounting upgrades

Cockpit teak professionally sanded and refinished prior to delivery

Radome antenna removed, inspected, and refinished, including overhaul of mounting hardware

New satellite TV antenna installed to restore the onboard SAT-TV system

New custom bedspreads supplied throughout the accommodation areas

Non-slip deck surfaces completely refurbished and repainted

Air intake vents refinished as part of the vessel's cosmetic upgrade programme

Helm and co-pilot seats modified and ergonomically improved for enhanced comfort and visibility while seated or standing

Additional 220V power outlet and SAT-TV connection installed at the cockpit wet bar area

Generator exhaust/water separator system repositioned and upgraded in the engine room

Hard-top support pillars locally restored, repainted and polished

New Gianneschi 24V backup freshwater pump installed, including electrical connections and mounting system

Main seawater intakes inspected, serviced and cleaned as part of the annual maintenance program

Works 2024

Recent Maintenance & Upgrades

Routine engine service carried out by an authorized Caterpillar (CAT) service center

Routine maintenance of Arneson surface drives performed by an authorized Arneson service center

Routine generator service completed by an authorized service provider

Inspection and maintenance of all electric motors onboard

Full service and cleaning of the air-conditioning systems

Inspection and cleaning of the main seawater intakes in the transom area as part of the annual maintenance program

Electrical System Upgrades

Installation of six Victron Energy AGM service batteries (12V / 125Ah)

Installation of Optima Red Top starting batteries (12V / 50Ah / 850 CCA)

Hydraulic system modification allowing direct freshwater supply from shore connection

Installation of a secondary inverter and battery charger system

New Victron Phoenix Compact C24/1600 inverter (24V / 1600VA)

Installation of a second battery charger with 1/2 selector switch

Installation of a second air-conditioning circulation pump

Comfort & Exterior Improvements

FURTHER INFORMATION

Transparent hard-top enclosure screens installed

Custom aft sunshade with stainless-steel support stanchions for the aft sunbathing area

Replacement of the galley cooktop

Full professional polishing of the vessel

Repainting of the swimming platform

The Company offers the details of this vessel in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the condition of the vessel. A buyer should instruct his agents, or his surveyors, to investigate such details as the buyer desires validated. This vessel is offered subject to prior sale, price change, or withdrawal without notice.

LOOPING



LOOPING



LOOPING



LOOPING



LOOPING



LOOPING



LOOPING

